20050601.ba v03_n813.bam.20050601

>From ???@??? Wed Jun 1 00:00:30 2005 -0500
Date: Wed, 1 Jun 2005 00:00:07 CDT
From: Old Tube Radios <boatanchors@theporch.com>
To: Old Tube Radios <boatanchors@theporch.com>
Subject: BOATANCHORS digest 3813
Message-Id: <20050601050008.C84274071B@srvr1.theporch.com>

BOATANCHORS Digest 3813

Topics covered in this issue include:

  1) re Tungar bulbs
     by "John Gillespie" <jgillespie@porchlight.ca>
  2) Free S-38s
     by Jack Antonio <scr287@sbcglobal.net>
  3) HRO Coil ID
     by Robert Nickels <w9ran@oneradio.net>
  4) S-38s
     by Jack Antonio <scr287@sbcglobal.net>
  5) Re: HRO Coil ID
     by "k4pf@juno.com" <k4pf@juno.com>
  6) Tungar bulbs
     by "John Gillespie" <jgillespie@porchlight.ca>
  7) Communications Quarterly FS
     by john <johnmb@nc.rr.com>
  8) WTB: Decent communications receiver.
     by Meyer Gottesman <wrecktech@yahoo.com>
  9) Parting Out Hallicrafters HT-32A, SX-99, SX-71 and Swan 500
     by David Hollander <n7rk@cox.net>
 10) Military Collectors - Listen Up - FS: Antenna Base Mast AB-15/GR
     by Brian K Harris <brian.k.harris@philips.com>
 11) HP connectors needed
     by Mike Steussy - AE4R <ae4r@erols.com>

Message-ID: <003801c5656a$b040c260$8800a8c0@jgillespie>
From: "John Gillespie" <jgillespie@porchlight.ca>
To: Old Tube Radios <boatanchors@theporch.com>
Subject: re Tungar bulbs
Date: Mon, 30 May 2005 18:55:32 -0400
MIME-Version: 1.0
Content-Type: text/plain;
     charset="iso-8859-1"
Content-Transfer-Encoding: 7bit

Thanks Roy Morgan:

sorry for taking so long to get back to you and others regarding the tungar bulbs. The web sites you provided are great and very much appreciated. I will be passing the information on to the guy in Prince Edward Island tomorrow, along with full mention of the help from the boatanchor group. 73's John!

Message-ID: <429BA521.6060804@sbcglobal.net>
Date: Mon, 30 May 2005 16:43:29 -0700
From: Jack Antonio <scr287@sbcglobal.net>
MIME-Version: 1.0
To: Old Tube Radios <boatanchors@theporch.com>
Subject: Free S-38s
Content-Type: text/plain; charset=ISO-8859-1; format=flowed
Content-Transfer-Encoding: 7bit

I have a pair of S-38 project radios
that I will never get around to.
They are free, just pick up postage,
first come, first served.

First is an S-38 no suffix. No BFO
knob, but the whole BFO pitch thing
looks like a kluge of some sort. Phony
cardboard back cover, but other than that
looks in fair shape. Dial cord is off the
pulley.

Second is a fair to poor S-38C. One IF
can is disassembled in a plastic bag inside
the radio, no back cover.

Both are guaranteed NOT to work!

Thanks

Jack

Jack Antonio WA7DIA
scr287@sbcglobal.net

Message-ID: <429BC916.1090007@oneradio.net>
Date: Mon, 30 May 2005 21:16:54 -0500
From: Robert Nickels <w9ran@oneradio.net>
MIME-Version: 1.0

To: Old Tube Radios <boatanchors@theporch.com>
Subject: HRO Coil ID
Content-Type: text/plain; charset=ISO-8859-1; format=flowed
Content-Transfer-Encoding: 7bit

Can anyone remind me how to tell HRO-50 coils and HRO-60 coils apart?
I need to identify the ABCD coils for an HRO-60.

Thanks and 73,
Bob W9RAN

Message-ID: <429BD3AF.3090901@sbcglobal.net>
Date: Mon, 30 May 2005 20:02:07 -0700
From: Jack Antonio <scr287@sbcglobal.net>
MIME-Version: 1.0
To: Old Tube Radios <boatanchors@theporch.com>
Subject: S-38s
Content-Type: text/plain; charset=ISO-8859-1; format=flowed
Content-Transfer-Encoding: 7bit

The S-38s are spoken for, thanks!

Jack

Jack Antonio WA7DIA
scr287@sbcglobal.net

Mime-Version: 1.0
From: "k4pf@juno.com" <k4pf@juno.com>
Date: Tue, 31 May 2005 02:59:52 GMT
To: Old Tube Radios <boatanchors@theporch.com>
Cc: boatanchors@theporch.com
Subject: Re: HRO Coil ID
Content-Type: text/plain
Message-Id: <20050530.200031.10161.210272@webmail18.lax.untd.com>

Hi,

The HRO-60 coils have an ID plate on each coil tray;
the HRO-50 coils have the ID letter engraved right on the coil tray
front panel.

The C and D coils will work the same in either receiver.
The A and B coils are for different first IF frequencies,
and are therefore not interchangeable between the HRO-50 and 60.

73,
Ed Knobloch

-- Robert Nickels <w9ran@oneradio.net> wrote:
>Can anyone remind me how to tell HRO-50 coils and HRO-60 coils apart?
>I need to identify the ABCD coils for an HRO-60.

>Thanks and 73,
>Bob W9RAN

Message-ID: <000b01c565f8$37d30c00$8800a8c0@jgillespie>
From: "John Gillespie" <jgillespie@porchlight.ca>
To: Old Tube Radios <boatanchors@theporch.com>
Subject: Tungar bulbs
Date: Tue, 31 May 2005 11:48:39 -0400
MIME-Version: 1.0
Content-Type: text/plain;
     charset="iso-8859-1"
Content-Transfer-Encoding: 7bit

hello David Stinson,
     we have a friend in PEI Canada
with a Willard battery Charger, looking for tungar
info. At this point we think its a tungar he needs we dont
know which one.   73's John!

Message-Id: <6.2.1.2.2.20050531155414.02e86b88@pop-server.nc.rr.com>
Date: Tue, 31 May 2005 15:56:08 -0400
To: Old Tube Radios <boatanchors@theporch.com>
From: john <johnmb@nc.rr.com>
Subject: Communications Quarterly FS
Mime-Version: 1.0
Content-Type: text/plain; charset=us-ascii; format=flowed

18 Issues of Communications Quarterly, in excellent condition.

The issues span from 91 to 99.

All for $25 plus postage

Thank you!
John

--
No virus found in this outgoing message.
Checked by AVG Anti-Virus.
Version: 7.0.322 / Virus Database: 267.3.0 - Release Date: 5/30/2005

Message-ID: <20050531200651.50770.qmail@web51004.mail.yahoo.com>
Date: Tue, 31 May 2005 13:06:50 -0700 (PDT)
From: Meyer Gottesman <wrecktech@yahoo.com>
Subject: WTB: Decent communications receiver.
To: Old Tube Radios <boatanchors@theporch.com>
MIME-Version: 1.0
Content-Type: text/plain; charset=iso-8859-1
Content-Transfer-Encoding: 8bit

I would like to buy a decent communications receiver
which is not pegged at an EBAY price! Hi!

Examples of receivers that hold special interest:

a-Collins 75A-4. Late S/N. 3800 and up.

b-Hallicrafters SX-115.

c-Navy WW II RBC. w/matching 115 vac supply.

d-RCA AR-88 or CR-88.

e-Racal...please advise.

f-Harris....please advise.

g-Watkins-Johnson.

73,

Meyer Gottesman, W6GIV
Macon, GA.
Tel: (478)741-1710.

_____
Do you Yahoo!?
Yahoo! Small Business - Try our new Resources site
http://smallbusiness.yahoo.com/resources/

Message-ID: <429CD5DF.8050409@cox.net>
Date: Tue, 31 May 2005 14:23:43 -0700
From: David Hollander <n7rk@cox.net>
MIME-Version: 1.0
To: Old Tube Radios <boatanchors@theporch.com>
Subject: Parting Out Hallicrafters HT-32A, SX-99, SX-71 and Swan 500
Content-Type: text/plain; charset=us-ascii; format=flowed
Content-Transfer-Encoding: 7bit

Parting out Hallicrafters HT-32A, SX-99, SX-71 and Swan 500 radios.

The meter on the HT-32A has been spoken for and the main tuning knobs on all four radios are gone. Pretty much everything else is available.

What do you need?

Dave N7RK

--
****
Dave N7RK Boatanchors Home Page: http://members.cox.net/n7rk
Phoenix, Arizona *DXCC Honor Roll* *WAZ#22 - 75 Meter SSB*

ex-XE2/N7RK, N7RK/ZB2, VK2ERK, ZM0AJN, WB6NRK, WN6IWX

Boatanchor and Antique Radio Collector

To: Old Tube Radios <boatanchors@theporch.com>
Subject: Military Collectors - Listen Up - FS: Antenna Base Mast AB-15/GR
MIME-Version: 1.0
Message-ID: <OF4156C0F6.063AB9CD-
ON88257012.005CD708-86257013.00112D6E@philips.com>
From: Brian K Harris <brian.k.harris@philips.com>
Date: Tue, 31 May 2005 22:06:53 -0500
Content-Type: multipart/alternative; boundary="=_alternative 00112D6786257013_="

This is a multipart message in MIME format.
--=_alternative 00112D6786257013_=
Content-Type: text/plain; charset="US-ASCII"

I have a new, in-the-box (as in, unopened) antenna base mast AB-15/GR for sale. Although I do not have XRAY vision, I believe this unit consists of two dark brown ceramic sections that form the base and a flexible green, rubber coated mast that accepts copper plate steel antenna sections. At the bottom there is an SO-239 socket. The U.S. government probably paid several hundred dollars for these things. I only want $15 plus shipping.

P.S. I've got 1 or 2 used ones around that I could be talked out of too.

Brian K. Harris, Account Manager, South Central Region

Philips Semiconductors
2140 Lake Park Boulevard, Suite 200
Richardson, Texas 75080 USA

Office: 972 705-2484
Mobile: 214-763-5977
Fax: 972-705-2450
Email: brian.k.harris@philips.com

--=_alternative 00112D6786257013_=
Content-Type: text/plain; charset=us-ascii
Content-Transfer-Encoding: 7bit

* *
*   ---REMAINDER OF MESSAGE TRUNCATED---   *
*   This post contains a forbidden message format   *
* (such as an attached file, a v-card, HTML formatting) *
*   Mail Lists at theporch.com only accept PLAIN TEXT   *
* If your postings display this message your mail program *
* is not set to send PLAIN TEXT ONLY and needs adjusting *
* *

--=_alternative--

Message-ID: <429D0AD8.7030807@erols.com>
Date: Tue, 31 May 2005 21:09:44 -0400
From: Mike Steussy - AE4R <ae4r@erols.com>
MIME-Version: 1.0
To: Old Tube Radios <boatanchors@theporch.com>
CC: "Wehle, Kurt - WA4SMI" <opelnut@erols.com>
Subject: HP connectors needed
Content-Type: text/plain; charset=us-ascii; format=flowed
Content-Transfer-Encoding: 7bit

Ahoy! My buddy Kurt WA4SMI, who puts his Valiant and HQ-170 on the air from time to time, found some Hewlett Packard equipment at a hamfest near Baltimore last weekend. Unfortunately he still needs a cable with a 24 pin female connector, HP part nr 1251-0054, on one end and the mating 24 pin male connector, HP part nr 1251-0055 on the other end. He's hoping he can find just the connectors and make his own extender cable. He would be grateful for any help or advice in finding these

connectors. I would gladly relay replies to Kurt, or you can contact him directly at:

opelnut@erols.com

Thanks and 73,
Mike Steussy AE4R

End of BOATANCHORS Digest 3813
****